



■ Sch80

※炭素鋼

※Kは最小寸法を示します。

mm

A呼称	B呼称	B	F	C	K	L
8A	1/4	14.3	22.0	10.0	4.5	16.0
10A	3/8	17.8	27.0	13.0	5.0	20.0
15A	1/2	22.2	32.0	13.0	6.1	21.0
20A	3/4	27.7	38.0	15.0	7.0	24.0
25A	1	34.5	46.0	16.0	8.3	27.0
32A	1・1/4	43.2	57.0	18.0	9.6	29.0
40A	1・1/2	49.1	63.0	19.0	10.5	32.0
50A	2	61.1	75.0	22.0	12.2	36.0
65A	2・1/2	77.1	95.0	26.0	15.3	43.0
80A	3	90.0	110.0	29.0	17.3	48.0
100A	4	115.4	140.0	35.0	22.4	59.0

■ Sch80

※ステンレス鋼

※Kは最小寸法を示します。

mm

A呼称	B呼称	B	F	C	K	L
8A	1/4	14.3	22.0	10	4.5	14.6
10A	3/8	17.8	28.0	10	5.0	15.6
15A	1/2	22.2	32.0	10	6.1	16.6
20A	3/4	27.7	38.0	13	7.0	20.2
25A	1	34.5	46.0	13	8.3	21.7
32A	1・1/4	43.2	55.0	13	9.6	22.7
40A	1・1/2	49.1	65.0	13	10.5	23.7
50A	2	61.1	75.0	16	12.2	28.9
65A	2・1/2	77.1	95.0	16	15.3	31.9
80A	3	90.0	110.0	16	17.3	33.9